



# FORD 2G B+ PLUG CHARGE WIRE MODIFY




Crimp, insulate and solder new copper eye terminal provided with this alternator

This wire will no longer be used



Cut off original B+ charge wire plug as shown, cut back 1" from plug.



No longer used